

PRECISION 3+ POWERMETER



Works with
Apple Find My



QUICK START GUIDE

FEATURES



APPLE FIND MY

Offering the peace of mind in knowing where your power meter is.



BATTERY LIFE

With up to 800 hours of battery life, you won't have to worry about changing your battery for years to come.




ACCURACY IN 3D

With +/- 1% accuracy, 4iiii is the only crank-based power meter to use 3 strain gauges to measure all forces in your pedal stroke.




AUTOMATIC TERRAIN SELECTOR

Detects the terrain you're riding on for more responsive cadence and power feedback/data. Ride the roads less traveled with confidence.



ULTRA LOW PROFILE

With an ultra low profile design, the PRECISION 3+ Powermeter is compatible with more bike frames than ever before.




LIGHT WEIGHT

At only 9 grams the PRECISION 3+ Powermeter weighs about the same as a sip from your water bottle.

1. INSTALLATION

Install your crank with Precision 3+ Powermeter following the crank manufacturer's instructions.

The steps to install the crank vary between models. Follow the manufacturer's instructions, or consult your local bike mechanic for assistance. Installation instructions for your new Shimano crank are included with the Ride Ready option.



2. 4iiii APP

Wake up PRECISION 3+ by rotating the crank 3-4 times.




Pair with the 4iiii app for updates

1. Select 'add device'
2. Select your power meter and press pair.
3. Perform any updates.

3. DISPLAY UNIT

Pair your power meter with a compatible display unit using ANT+ or Bluetooth.


1. Turn on your display unit.
2. Spin the crank 3-4 times to wake up your power meter.
3. Navigate to the "sensors" menu on your display unit.
4. Add your power meter



4. ZERO OFFSET

Perform a zero offset, sometimes referred to as a calibration.

1. Unclip and dismount. Hold the bike upright and stationary, and position the crank arms at 12 and 6 o'clock, with the non-drive side crank arm down.
2. Select "Zero" or "Calibrate" on your display unit.



5. APPLE FIND MY

Connect to the Apple Find My app (For iOS users)

1. Remove and reinstall the battery on your PRECISION 3+ Powermeter **three times (x3)** to trigger Apple Find My pairing mode.
2. From the Apple Find My app, add your PRECISION 3+ Powermeter.



TIPS

- **DO NOT** expose your power meter to degreasers, or abrasive or corrosive cleaning agents. Don't pressure wash your power meters.
- Battery levels can be checked using the 4iiii App.
- For best results, perform a zero offset before each ride.
- The battery cap twists off with no tools required.
- The PRECISION 3+ Powermeter comes with a pre-installed battery. When needed, replace with any CR2032 battery.
- Store your power meter in temperatures no colder than -40°C (-40° F) and no warmer than 60°C (140° F)

**THANK YOU FOR PURCHASING
PRECISION 3+ POWERMETER**

For the complete user manual go to 4iiii.com/support